


FIG. 1

FIG. 2



AE Setting Process
START

S1 Unspecified
Time
Elapsed? NO

YES

S2 Set
Exposure
Amounts $1/2000$

S3 Exposure

S4 Set Exposure
Amount M $1/250$

S5 Exposure

S6 Readout
Exposure
Amount S

S7 Set Exposure
Amount L $1/30$

S8 Exposure

S9 Readout
Exposure
Amount M

S10 Calculate
and Store
Exposure Amounts

1

FIG. 3a





FIG. 3b


FIG. 4



Level E	α (EV)
over 200	$-\frac{3}{2}$
$160 \leq E < 200$	-1.0
$140 \leq E < 160$	$-\frac{1}{2}$
$132 \leq E < 140$	$-\frac{1}{4}$
$125 \leq E < 132$	
$118 \leq E < 125$	$+\frac{1}{4}$
$100 \leq E < 118$	$+\frac{1}{2}$
$70 \leq E < 100$	+1.0
less than 70	$+\frac{3}{2}$

FIG. 5

FIG. 6






FIG. 8

Prior Art